

DIN EN 1279-6:2021-05 (E)

Glass in building - Insulating glass units - Part 6: Factory production control and periodic tests

Contents		Page
European foreword		5
1 Scope		7
2 Normative references		7
3 Terms and definitions and symbols		7
3.1 Terms and definitions		7
3.2 Symbols		8
4 Factory production control requirements		8
4.1 General		8
4.2 Organization		8
4.2.1 Responsibility and authority		8
4.2.2 Management representative for factory production control		8
4.2.3 Management review		8
4.3 Factory production control system		8
4.3.1 General		8
4.3.2 Personnel		9
4.3.3 Documentation		9
4.4 Equipment		9
4.4.1 Testing		9
4.4.2 Manufacturing		9
4.4.3 Inspection and testing		9
4.4.4 Non-complying materials / products		9
Annex A(normative) Inspection and testing tables of insulating glass units		10
A.1 General		10
A.2 Specific requirements		11
A.3 Use of proxy testing		11
Annex B(normative) Periodic testing and inspection		33
B.1 General		33
B.2 Frequency and sampling		33
B.2.1 Frequency		33
B.2.2 Sampling		33
B.3 Conformity to the system description		33
B.3.1 Inspection		33
B.3.2 Requirements		33
B.3.3 Corrective actions		34
B.4 Moisture penetration index and gas concentration		34
B.4.1 General		34
B.4.2 Procedure		34
B.4.3 Test procedure		34
B.4.4 Requirement		35
B.4.4.1 Requirement on Ti and moisture penetration index		35
B.4.4.2 Requirements on gas concentration		35
B.5 Corrective Actions in case of non-conformity		35
B.6 Report		35

Annex C(informative) Adhesion test for leaded light strip	36	
C.1 Purpose	36	
C.2 Equipment	36	
C.3 Test specimen	36	
C.4 Procedure	36	
C.5 Test report	37	
Annex D(informative) Sealant, adhesion measurements	38	
D.1 General	38	
D.2 Standard method	38	
D.2.1 Instruments	38	
D.2.2 Test specimens	38	
D.2.2.1 Glass-glass	specimen	38
D.2.2.2 Spacer-spacer.....	specimen	39
D.2.3 Test procedure	39	
D.2.4 Test report	39	
D.3 Other methods	39	
D.3.1 Tensile test	39	
D.3.2 Butterfly test	40	
Annex E(informative) Sealants, hardness measurements	41	
E.1 General	41	
E.2 Instruments	41	
E.3 Test specimen	41	
E.4 Measurement	42	
E.5 Report	42	
Annex F(informative) Two component sealants: check on the thoroughness of mixing	43	
F.1 Purpose	43	
F.2 Test specimen	43	
F.3 Test procedure	43	
F.4 Report	43	
Annex G(informative) Tightness check of hollow spacer closed by welding on the back	44	
G.1 Purpose	44	
G.2 Equipment	44	
G.3 Test specimen	44	
G.4 Procedure	44	
G.5 Test report	44	
Annex H(informative) Desiccant, water adsorption capacity check	45	
H.1 General	45	
H.2 Determination of the water adsorption capacity of desiccant in bulk	45	
H.2.1 Principle	45	
H.2.2 Equipment	45	
H.2.3 Method	45	
H.3 Determination of the water adsorption capacity of polymeric matrix incorporating desiccant	46	
Annex I(informative) Desiccant Matrix Adhesion test in u-channels	47	
I.1 General	47	
I.2 Materials	47	
I.3 Test procedure	47	
I.4 Requirement	47	

Annex J(informative) Adhesion tests for insulating glass units with prefabricated flexible spacer incorporating desiccant	48
J.1 Adhesion test of spacer to sealant	48
J.1.1 General	48
J.1.2 Materials	48
J.1.3 Test preparation and procedure	48
J.1.4 Requirements	48
J.2 Wet out strain and shear test	49
J.2.1 Materials	49
J.2.2 Test procedure	49
J.2.3 Requirements	53
Annex K(informative) Reference method for dew point temperature measurement	54
K.1 General	54
K.2 Apparatus and materials	54
K.3 Procedure	54
Bibliography	56