

ISO 22476-1:2022-12 (E)

Geotechnical investigation and testing - Field testing - Part 1: Electrical cone and piezocone penetration test

| Contents | | Page |
|--------------------|---|-------------|
| Foreword | | v |
| Introduction | | vi |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms, definitions and symbols | 1 |
| 3.1 | Terms and definitions | 2 |
| 3.2 | Symbols | 8 |
| 4 | Equipment | 11 |
| 4.1 | General | 11 |
| 4.1.1 | Tolerances | 11 |
| 4.1.2 | Gaps and soil seals | 11 |
| 4.2 | Cone penetrometer | 11 |
| 4.3 | Surface roughness and hardness | 11 |
| 4.4 | Cone | 12 |
| 4.5 | Friction sleeve | 13 |
| 4.6 | Filter element | 14 |
| 4.6.1 | General filter location | 14 |
| 4.6.2 | Pore pressure u1 | 14 |
| 4.6.3 | Pore pressure u2 | 15 |
| 4.6.4 | Pore pressure u3 | 15 |
| 4.7 | Pushrods | 15 |
| 4.8 | Measuring system | 15 |
| 4.8.1 | Accuracy | 15 |
| 4.8.2 | Sensors for cone resistance and sleeve friction | 16 |
| 4.8.3 | Sensor for pore pressure | 16 |
| 4.8.4 | Sensor for inclination | 16 |
| 4.8.5 | Sensor for temperature | 16 |
| 4.8.6 | Measuring of penetration length | 16 |
| 4.8.7 | Raw data | 16 |
| 4.9 | Thrust machine | 17 |
| 5 | Test procedures | 17 |
| 5.1 | Selection of equipment, procedures and evaluation of results | 17 |
| 5.1.1 | General | 17 |
| 5.1.2 | Calibration and verification requirements | 17 |
| 5.1.3 | Cone penetrometer class conformity assessment | 18 |
| 5.2 | Position and verticality of thrust machine | 20 |
| 5.3 | Preparation of the test | 20 |
| 5.4 | Pushing of the cone penetrometer | 21 |
| 5.5 | Use of friction-reducing techniques | 21 |
| 5.6 | Frequency of test data recording | 21 |
| 5.7 | Registration of penetration length | 21 |
| 5.8 | Pore pressure dissipation test (PPDT) | 22 |
| 5.9 | Test completion | 22 |
| 5.10 | Evaluation of CPT/CPTU in relation to test category | 23 |
| 5.11 | Equipment checks and calibrations | 24 |

| | | |
|--|------------------------------------|----|
| 5.12 | Safety requirements | 24 |
| 6 | Test results | 24 |
| 6.1 | Measured parameters | 24 |
| 6.2 | Correction of parameters | 25 |
| 6.3 | Calculated parameters | 27 |
| 7 | Reporting | 27 |
| 7.1 | General | 27 |
| 7.2 | Reporting of test results | 27 |
| 7.2.1 | General information | 27 |
| 7.2.2 | Location of the test | 28 |
| 7.2.3 | Test equipment | 28 |
| 7.2.4 | Test results | 29 |
| 7.3 | Presentation of test results | 29 |
| Annex A (informative) Suitability of test methods | | 31 |
| Annex B (normative) Maintenance, checks and calibration | | 34 |
| Annex C (informative) Calibration report example | | 52 |
| Annex D (normative) Calculation of penetration depth | | 62 |
| Annex E (informative) Correction of sleeve friction for water pressure | | 63 |
| Annex F (informative) Preparation of the piezocone | | 64 |
| Annex G (informative) Friction reduction techniques | | 65 |
| Bibliography | | 66 |