

ISO 5660-1:2002-12 (E)

Reaction-to-fire tests - Heat release, smoke production and mass loss rate - Part 1: Heat release rate (con e calorimeter method)

Contents		Page
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	2
5	Principle	3
6	Apparatus	3
7	Suitability of a product for testing	6
8	Specimen construction and preparation	7
9	Test environment	9
10	Calibration	9
11	Test procedure	12
12	Calculations	14
13	Test report	16
Annexes A Commentary and guidance notes for operators		24
B	Resolution, precision and bias	26
C	Mass loss rate and effective heat of combustion	31
D	Testing in the vertical orientation	32
E	Calibration of the working heat flux meter	35
F	Calculation of heat release with additional gas analysis	36
Bibliography		39