

ISO 14934-3:2006-09 (E)

Fire tests - Calibration and use of heat flux meters - Part 3: Secondary calibration method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	1
5	Apparatus	2
5.1	Radiant source	2
5.2	Mounting arrangements	2
5.3	Instrumentation	2
5.4	Additional equipment	3
6	Test environment	3
6.1	Room	3
6.2	Draught	3
7	Setting up procedure	3
7.1	General	3
7.2	Mounting and alignment of heat flux meters	3
8	Typical calibration procedures	4
9	Calculation of results	4
9.1	General	4
9.2	Graphical presentation	5
9.3	Mathematical presentation	5
9.4	Uncertainty in regression curve	5
10	Test report	6
Annex A (informative) Accuracy of calibration		7
Annex B (informative) Care of heat flux meters		8
Annex C (informative) Guidance notes		9
Annex D (informative) Procedure recommended for maintenance of a secondary standard of irradiance at a test laboratory		11
Bibliography		14