

ISO/TS 14934-4:2007-02 (E)

Fire tests - Calibration of heat flux meters - Part 4: Guidance on the use of heat flux meters in fire tests

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	General information on heat flux meters	1
4.1	General	1
4.2	Principle of measurement	2
4.3	Design of heat flux meter	3
4.4	Measurement characteristics	5
4.5	Physical shape of heat flux meter	7
5	Attachments to heat flux meters	8
5.1	Air purging	8
5.2	Windows	9
5.3	Cooling system	10
6	Selection of a suitable heat flux meter	12
6.1	General	12
6.2	Range of measurement	12
6.3	Type, dimensions and orientation	13
6.4	View angle	13
6.5	Response time	13
6.6	Sensitivity to convective heat transfer	13
7	Performing a measurement	14
7.1	Installation	14
7.2	Target surface	15
7.3	Electronics	15
7.4	Relationship between output voltage and total heat flux	15
8	Calibration	16
8.1	Secondary standard heat flux meter	16
8.2	Working standard heat flux meters	16
8.3	Frequency of calibration	16
9	Maintenance	17
9.1	Absorber	17
9.2	Wiring	17
9.3	Water supply	17
10	Use of heat flux meters in fire tests	17
10.1	General	17
10.2	Ignitability test (see ISO 5657)	17
10.3	Spread of flame test (see ISO 5658, all parts)	17
10.4	Heat release, smoke production and mass loss (see ISO 5658, all parts, and ISO 17554) ..	18

10.5	Full-scale room test for surface products (see ISO 9705)	18
10.6	Façade tests (see ISO 13785-2)	18
10.7	Spread of flame test for floor coverings (see ISO 9239, all parts)	18
10.8	Intermediate-scale heat-release calorimeter (ICAL) (see ISO/TR 14696)	18
	Bibliography	19