

# DIN EN ISO 7726:2002-04 (E)

## Ergonomics of the thermal environment - Instruments for measuring physical quantities (ISO 7726:1998)

---

### Contents

	Page
1 Scope.....	4
2 Normative reference .....	4
3 General .....	4
4 Measuring instruments .....	5
5 Specifications relating to measuring methods .....	8
<b>Annex A</b> Measurement of air temperature .....	<b>15</b>
<b>Annex B</b> Measurement of the mean radiant temperature .....	<b>17</b>
<b>Annex C</b> Measurement of plane radiant temperature .....	<b>31</b>
<b>Annex D</b> Measurement of the absolute humidity of the air .....	<b>38</b>
<b>Annex E</b> Measurement of air velocity.....	<b>48</b>
<b>Annex F</b> Measurement of surface temperature .....	<b>51</b>
<b>Annex G</b> Measurement of operative temperature.....	<b>52</b>
<b>Annex H</b> Bibliography.....	<b>54</b>