

DIN ISO 11421:2010-10 (E)

Optics and optical instruments - Accuracy of optical transfer function (OTF) measurement (ISO 11421:1997)

Contents		Page
National foreword		3
National Annex NA (informative) Bibliography		3
Introduction		4
1	Scope	5
2	Normative reference	5
3	Definitions and symbols	5
4	Sources of inaccuracy in measuring equipment	7
5	Methods of assessing levels of accuracy	14
6	Calculation of overall accuracy of a measurement	22
7	Specifying a general equipment accuracy	23
8	Routine performance evaluation	26
Annex A (normative) Accuracy of PTF measurement		28
Annex B (informative) Determination of rate of change of MTF various parameters		29
Annex C (informative) Example calculation of NAV		31
Annex D (informative) Bibliography		34