

DIN ISO 11421:2010-10 (E)

Optics and optical instruments - Accuracy of optical transfer function (OTF) measurement (ISO 11421:1997)

Contents	Page
National foreword	3
National Annex NA (informative) Bibliography	3
Introduction	4
1 Scope	5
2 Normative reference	5
3 Definitions and symbols	5
4 Sources of inaccuracy in measuring equipment	7
5 Methods of assessing levels of accuracy	14
6 Calculation of overall accuracy of a measurement	22
7 Specifying a general equipment accuracy	23
8 Routine performance evaluation	26
Annex A (normative) Accuracy of PTF measurement	28
Annex B (informative) Determination of rate of change of MTF various parameters	29
Annex C (informative) Example calculation of NAV	31
Annex D (informative) Bibliography	34