

ISO 23160:2011-06 (E)

Watch cases and accessories - Tests of the resistance to wear, scratching and impacts

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Wear resistance	2
4.1	Wear test using moving ceramic chips	2
4.2	Wear test using continuous friction against a textile belt	4
4.3	Wear test by reciprocating movement against an abrasive surface	7
5	Scratch resistance	10
5.1	Objective	10
5.2	Description of test	10
5.3	Abrasive load	10
5.4	Operating procedure	10
5.5	Calibration	11
5.6	Evaluation of results	11
6	Impact resistance	11
6.1	Objective	11
6.2	Description of test	11
6.3	Abrasive material	12
6.4	Operating procedure	12
6.5	Calibration	13
6.6	Evaluation of results	13
Annex A (normative) Visual inspection of watch cases and wristlets or test samples after testing for resistance to wear, scratching and impacts		14
Annex B (informative) Examples of machines and abrasive elements used for the tests described in 4.1 and Clause 5		15
Bibliography		16