

# ISO/TR 21254-4:2011-09 (E)

## Lasers and laser-related equipment - Test methods for laser-induced damage threshold - Part 4: Inspection, detection and measurement

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Damage detection methods .....	1
4.1	General .....	1
4.2	Summary of damage detection methods .....	2
4.3	Collection of radiation from the sample .....	3
4.3.1	Scatter detection techniques .....	3
4.3.2	Detection of plasma and thermal radiation .....	4
4.3.3	Fluorescence .....	4
4.4	Detection of changes in reflectance or transmittance and imaging techniques .....	5
4.4.1	Online detection of changes in reflectance or transmittance .....	5
4.4.2	Online microscopy .....	7
4.5	Photothermal detection schemes .....	8
4.5.1	General .....	8
4.5.2	Photothermal deflection and surface thermal lensing .....	8
4.5.3	Mirage effect .....	10
4.6	Transient pressure sensing .....	10
5	Inspection techniques after the laser test sequence .....	11
5.1	General .....	11
5.2	Nomarski microscopy .....	12
5.3	Microscopic image comparator .....	12
5.4	Laser scanning microscopy .....	14
5.5	Mapping techniques .....	15
5.6	Electron microscopy .....	16
5.7	Atomic force microscopy .....	17
5.8	Confocal microscopy .....	17
Bibliography .....		19