

ISO/TR 21254-4:2011-09 (E)

Lasers and laser-related equipment - Test methods for laser-induced damage threshold - Part 4: Inspection, detection and measurement

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Damage detection methods	1
4.1	General	1
4.2	Summary of damage detection methods	2
4.3	Collection of radiation from the sample	3
4.3.1	Scatter detection techniques	3
4.3.2	Detection of plasma and thermal radiation	4
4.3.3	Fluorescence	4
4.4	Detection of changes in reflectance or transmittance and imaging techniques	5
4.4.1	Online detection of changes in reflectance or transmittance	5
4.4.2	Online microscopy	7
4.5	Photothermal detection schemes	8
4.5.1	General	8
4.5.2	Photothermal deflection and surface thermal lensing	8
4.5.3	Mirage effect	10
4.6	Transient pressure sensing	10
5	Inspection techniques after the laser test sequence	11
5.1	General	11
5.2	Nomarski microscopy	12
5.3	Microscopic image comparator	12
5.4	Laser scanning microscopy	14
5.5	Mapping techniques	15
5.6	Electron microscopy	16
5.7	Atomic force microscopy	17
5.8	Confocal microscopy	17
Bibliography		19