

# ISO 9022-6:2015-03 (E)

## Optics and photonics - Environmental test methods - Part 6: Dust

---

<b>Contents</b>		<b>Page</b>
Foreword.....		iv
Introduction.....		vi
<b>1</b> <b>Scope</b> .....		<b>1</b>
<b>2</b> <b>Normative references</b> .....		<b>1</b>
<b>3</b> <b>General information and test conditions</b> .....		<b>1</b>
<b>4</b> <b>Conditioning method 52: Blowing dust</b> .....		<b>3</b>
<b>5</b> <b>Procedure</b> .....		<b>3</b>
5.1    General.....		3
5.2    Preconditioning.....		3
5.3    Recovery.....		4
<b>6</b> <b>Environmental test code</b> .....		<b>4</b>
<b>7</b> <b>Specification</b> .....		<b>4</b>