

ISO 9022-6:2015-03 (E)

Optics and photonics - Environmental test methods - Part 6: Dust

Contents		Page
Foreword.....		iv
Introduction.....		vi
1 Scope		1
2 Normative references		1
3 General information and test conditions		1
4 Conditioning method 52: Blowing dust		3
5 Procedure		3
5.1 General.....		3
5.2 Preconditioning.....		3
5.3 Recovery.....		4
6 Environmental test code		4
7 Specification		4