

# ISO 9022-14:2015-04 (E)

## Optics and photonics - Environmental test methods - Part 14: Dew, hoarfrost, ice

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	General information and test conditions .....	1
4	Conditioning .....	1
5	Procedure .....	2
5.1	General .....	2
5.2	Preconditioning .....	2
5.3	Test sequence .....	2
5.3.1	Conditioning method 75, degree of severity 01; conditioning method 76, degrees of severity 01 and 02 .....	2
5.3.2	Conditioning method 76, degree of severity 03 .....	3
5.3.3	Conditioning method 77 .....	3
5.4	Recovery .....	3
5.5	Final test .....	3
6	Environmental test code .....	3
7	Specification .....	4
Annex A (informative)	Explanatory notes .....	5