

# ISO 16975-3:2017-09 (E)

## Respiratory protective devices - Selection, use and maintenance - Part 3: Fit-testing procedures

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	General .....	3
5	Competent fit-test operator .....	4
5.1	General .....	4
5.2	Qualifications .....	4
5.2.1	General .....	4
5.2.2	Knowledge of RPD used for the fit test .....	4
5.2.3	Knowledge of the fit-test method .....	4
5.2.4	Ability to set up and monitor the function of fit-test equipment .....	4
5.2.5	Ability to conduct the fit test .....	5
5.2.6	Ability to identify likely causes of fit-test failure .....	5
6	General fit-test considerations .....	5
6.1	Medical clearance .....	5
6.2	Training for RPD wearers .....	5
6.3	Interference concerns .....	6
6.3.1	Facial hair .....	6
6.3.2	Foreign material .....	6
6.3.3	Personal protective equipment (PPE) and other items that may interfere with fit6 6.3.4 Other conditions that can adversely affect fit .....	6
6.4	Frequency of fit testing .....	7
6.5	RPD used for fit testing .....	7
6.5.1	General .....	7
6.5.2	RPD used for QLFT .....	7
6.5.3	RPD used for QNFT .....	8
6.5.4	Sampling for aerosol systems .....	8
6.5.5	Maintenance of equipment and RPD used for fit testing .....	8
6.6	Selecting RPD .....	8
6.6.1	General .....	8
6.6.2	Comfort-assessment period .....	9
6.6.3	Required fit factor .....	9
7	Fit-test records .....	10
8	Fit-testing procedures .....	10
8.1	General .....	10
8.2	Respiratory interface .....	11
8.3	Briefing the fit-test subject .....	11
8.4	Fit-test exercises .....	11
8.5	Qualitative fit testing (QLFT) .....	12
8.5.1	General .....	12

8.5.2	Aerosol qualitative fit tests .....	12
8.5.3	Taste-threshold-screening .....	13
8.5.4	Fit testing .....	14
8.5.5	Vapour qualitative fit test with isoamyl acetate (banana oil) .....	15
8.5.6	IAA fit-testing procedure .....	17
8.6	Quantitative fit testing (QNFT) .....	18
8.6.1	General .....	18
8.6.2	Generated aerosol quantitative fit-test procedure .....	18
8.6.3	Ambient aerosol condensation nuclei-counting (CNC) instrument quantitative fit-test procedure .....	20
8.6.4	Controlled negative-pressure (CNP) REDON quantitative fit-test procedure .....	22
Annex A (informative) Example of an evaluation form for RPD competent fit-test operator .....		25
Annex B (informative) Explanation of different RFF based on QNFT method .....		26
Annex C (informative) Criteria for evaluating new fit-test methods .....		27
Bibliography .....		28