

ISO 10110-18:2018-12 (E)

Optics and photonics - Preparation of drawings for optical elements and systems - Part 18: Stress bi refraction, bubbles and inclusions, homogeneity, and striae

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
3.1	Terms for stress birefringence	1
3.2	Terms for bubbles and inclusions	2
3.3	Terms for homogeneity and striae	2
4	Specification of raw material and finished assemblies	2
4.1	Raw material	2
4.2	Finished assemblies	2
5	Stress birefringence	3
5.1	Principle of specification	3
5.2	Indication in drawings	3
5.2.1	Indication codes	3
5.2.2	Structure of the indication	3
5.3	Examples of indications for stress birefringence	3
6	Bubbles and inclusions	3
6.1	General	3
6.2	Principle of specification	3
6.3	Indication in drawings	4
6.3.1	Indication codes	4
6.3.2	Structure of the indication	4
6.4	Accumulation rule	4
6.5	Concentration rule	5
6.6	Examples of indications for bubbles	5
7	Homogeneity and striae	5
7.1	General	5
7.2	Indication in drawings	5
7.2.1	Indication codes	5
7.2.2	Structure of the indication	6
7.3	Homogeneity	6
7.3.1	Principle of specification	6
7.3.2	Quality classes	6
7.3.3	Focus term	7
7.4	Striae	7
7.4.1	Principles of specification	7
7.4.2	Density classes for striae	7
7.4.3	Wavefront deviation classes for striae	7
7.4.4	Comparison of density and wavefront quality classes for striae	8
7.4.5	Multiple orthogonal directions	8
7.5	Examples of indications for homogeneity and striae	8

8	Indications for "no requirement" or "default"	9
9	Indications on drawings	9
9.1	Table field	9
9.2	Drawing field	9
10	Indications for other optical material tolerances	9
11	Examples of indications on drawings	9
11.1	Example 1: Raw material properties in the drawing region	9
11.2	Example 2: Finished part bubble specification	10
11.3	Example 3: Finished part, all three properties	10
11.4	Example 4: System example	11
11.5	Example 5: Tabulation example	11
	Annex A (informative) Stress optical constant and stress birefringence	12
	Annex B (informative) Guidance for stress birefringence in optical glass	13
	Annex C (informative) Guidance for bubble grades in optical glass	15
	Annex D (informative) Guidance for homogeneity in optical glass	18
	Annex E (informative) Guidance for striae in optical glass	20
	Bibliography	22