

ISO/TR 14999-2:2019-07 (E)

Optics and photonics - Interferometric measurement of optical elements and optical systems - Part 2: Measurement and evaluation techniques

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Measurement objects	1
4.1	Surfaces	1
4.1.1	Boundary surfaces of optical components	1
4.1.2	Reflection degree	2
4.1.3	Roughness	2
4.1.4	Topology of the regions (discontinuous regions)	2
4.1.5	Continuity of the surface; gradient of the surface	2
4.1.6	Stiffness of mirrors; finite-element-calculations	3
4.1.7	Temperature homogeneity of mirrors	3
4.1.8	Examples of measurement objects	3
4.2	Optical components in transmission	3
4.2.1	Single-pass versus double-pass testing	3
4.2.2	Windows (wavefront aberrations in transmission)	3
4.2.3	Prisms (wavefront aberrations and angle error)	3
4.2.4	Influence of temperature on the refractive index	3
4.3	Optical systems	4
4.3.1	Single-pass versus double-pass testing	4
4.3.2	Examination in the pupil	4
4.3.3	Chromatic aberrations	4
4.4	Indirect examination of the function of optical elements	4
4.4.1	Examination with different wavelengths	4
4.4.2	Examination with different beam paths	4
4.4.3	Tolerance range	4
5	Hardware aspects of an interferometer and test environment	4
5.1	General	4
5.2	Construction principles and influences on the quality of measurements	6
5.2.1	General	6
5.2.2	Intrinsic instrument errors and the principle of common path	7
5.2.3	Optical compensation of errors	8
5.2.4	Mathematical compensation of errors	9
5.2.5	Contrast as a function of the irradiance in test and reference arm: methods to attain equilibrium in both arms	10
5.2.6	Contrast as a function of performance of the light source	14
5.3	Test environment	16
5.3.1	General	16
5.3.2	Influence of vibrations	17
5.3.3	Influence of gravity and support of the test piece	18
6	Methods for evaluating the optical path difference	20
6.1	General	20

6.2	Visual inspection of interferograms	20
6.2.1	General	20
6.2.2	Example 1 -- Fizeau interferometer	20
6.2.3	Example 2 -- Twyman-Green interferometer	24
6.3	Manual evaluation of interferograms	26
6.4	Phase measurements with temporal carrier	28
6.4.1	General	28
6.4.2	Heterodyne interferometry	29
6.4.3	Phase lock interferometry (PLI)	30
6.4.4	Synchronous detection and phase-shifting interferometry	30
6.5	Phase measurements with spatial carrier	34
6.5.1	Fringe analysis by Fourier transform operations	34
6.5.2	Spatially synchronous fringe analysis	35
6.6	Removal of phase ambiguities (phase unwrapping)	37
6.7	Registration of wavefronts; coordinate systems, coordinate system definition	38
6.8	Polynomial and other representations of wavefronts	39
6.8.1	Representation of phase data	39
6.8.2	Zernike polynomials for a circular boundary	40
6.8.3	Use of Zernike polynomials for an elliptical boundary	40
6.8.4	Zernike-Tatian polynomials for a circular shape with a central hole (annular)	41
6.8.5	Legendre polynomials for a rectangle boundary	41
6.8.6	Orthogonal functions on "unusual areas"	41
7	Test reports and calibration certificates	41
7.1	General	41
7.2	Content of test reports and calibration certificates	42
7.3	Test reports	42
7.4	Calibration certificates	43
7.4.1	Basics	43
7.4.2	Specification	43
7.4.3	Adjustment or repair	43
7.5	Opinions and interpretations	43
7.6	Electronic transmission of results	43
7.7	Format of reports and certificates	44
7.8	Amendments to test reports and calibration certificates	44
8	Data format	44
	Annex A (informative) Orthogonal polynomials	45
	Bibliography	62