

DIN EN ISO 19734:2021-09 (E)

Eye and face protection - Guidance on selection, use and maintenance (ISO 19734:2021)

| Contents | | Page |
|-------------------------|---|-------------|
| European foreword | | 4 |
| Foreword | | 5 |
| Introduction | | 6 |
| 1 | Scope | 7 |
| 2 | Normative references | 7 |
| 3 | Terms and definitions | 7 |
| 4 | General | 8 |
| 4.1 | Structure of the human eye | 8 |
| 4.2 | Hazards and risks to the eye and face | 9 |
| 4.2.1 | Surrounding structures of the eye | 9 |
| 4.2.2 | Peri-orbital skin | 10 |
| 4.2.3 | Tears | 10 |
| 4.2.4 | Cornea and conjunctiva | 10 |
| 4.2.5 | Iris and lens | 10 |
| 4.2.6 | Retina | 11 |
| 4.2.7 | Optic nerve | 11 |
| 4.2.8 | Choroid and retinal pigment epithelium | 11 |
| 4.3 | The eye's defence system | 11 |
| 4.4 | Colour perception | 13 |
| 5 | Hazards and their consequences | 14 |
| 5.1 | General hazards | 14 |
| 5.1.1 | Mechanical hazards | 14 |
| 5.1.2 | Chemical hazards | 15 |
| 5.1.3 | Radiation hazards | 16 |
| 5.1.4 | Biological hazards | 17 |
| 5.1.5 | Convection heat | 18 |
| 5.2 | Application specific hazards | 18 |
| 5.2.1 | Laser hazards | 18 |
| 5.2.2 | Welding hazards | 19 |
| 5.2.3 | Electric arc hazards | 20 |
| 5.2.4 | Glass blowing hazards | 20 |
| 6 | Control of eye and face hazards | 21 |
| 6.1 | General | 21 |
| 6.2 | Screens | 22 |
| 6.2.1 | General | 22 |
| 6.2.2 | Recommended materials for screens | 23 |
| 6.2.3 | Selection of light-transmitting screens and curtains for arc welding operations 23 6.2.4 Illumination of the work area | 23 |
| 6.3 | Exhaust systems | 23 |
| 6.4 | Other methods | 23 |
| 7 | Selection and use of personal protective equipment (PPE) | 24 |
| 7.1 | General | 24 |

| | | |
|-------|---|----|
| 7.2 | Types of eye and face protectors | 24 |
| 7.2.1 | General | 24 |
| 7.2.2 | Selection process | 26 |
| 7.2.3 | Eye and face protection for those requiring vision correction | 32 |
| 7.2.4 | Material choice | 33 |
| 7.2.5 | Comfort, vision and fit | 34 |
| 7.2.6 | Application based selection | 35 |
| 7.3 | Checking the fit | 35 |
| 7.3.1 | Fit, comfort and compliance | 35 |
| 7.3.2 | Ensuring compliance with an eye protection programme | 46 |
| 8 | Care and maintenance | 46 |
| 8.1 | Hygiene and cleaning | 46 |
| 8.2 | Replacement of eye protectors | 47 |
| 9 | Compatibility | 47 |
| 9.1 | General | 47 |
| 9.2 | Eye protectors and respirators | 48 |
| 9.3 | Eye protectors and protective earmuffs | 48 |
| 9.4 | Helmet mounted face shields | 48 |
| 9.5 | Face shields and respirators | 48 |
| 9.6 | Eyewear with half-mask respirators | 48 |
| 10 | Eye and face protector marking | 48 |
| 11 | Special requirements for working conditions (e.g. hot, humid, dusty, fog, abrasion) | 49 |
| | Annex A (informative) Electric arc protective equipment combinations | 51 |
| | Annex B (informative) Marking of laser eye protectors | 53 |
| | Bibliography | 55 |