

# DIN ISO 9211-4:2023-07 (E)

## Optics and photonics - Optical coatings - Part 4: Specific test methods: abrasion, adhesion and resistance to water (ISO 9211-4:2022)

---

<b>Contents</b>		<b>Page</b>
<b>National foreword</b> .....		<b>3</b>
<b>National Annex NA (informative) Bibliography</b> .....		<b>5</b>
<b>Foreword</b> .....		<b>6</b>
<b>1</b>	<b>Scope</b> .....	<b>7</b>
<b>2</b>	<b>Normative references</b> .....	<b>7</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>7</b>
<b>4</b>	<b>Preparation prior to testing</b> .....	<b>7</b>
<b>5</b>	<b>Abrasion tests: cheesecloth/eraser test (conditioning method 01)</b> .....	<b>8</b>
5.1	General.....	8
5.2	Test conditions.....	8
5.2.1	General.....	8
5.2.2	Moderate abrasion test.....	8
5.2.3	Severe abrasion test.....	8
5.3	Degree of severity: abrasion – cheesecloth/eraser test (conditioning method 01).....	8
5.4	Recovery.....	9
5.5	Evaluation.....	9
<b>6</b>	<b>Adhesion test: tape test (conditioning method 02)</b> .....	<b>9</b>
6.1	General.....	9
6.2	Test conditions.....	9
6.3	Degree of severity: adhesion – tape test (conditioning method 02).....	10
6.4	Recovery.....	10
6.5	Evaluation.....	10
<b>7</b>	<b>Adhesion test: crosshatch test (conditioning method 03)</b> .....	<b>10</b>
7.1	General.....	10
7.2	Test conditions.....	10
7.3	Degree of severity.....	10
7.4	Conditioning.....	11
7.5	Recovery.....	11
7.6	Evaluation.....	11
<b>8</b>	<b>Resistance to water: exposure to water (conditioning method 04)</b> .....	<b>11</b>
8.1	General.....	11
8.2	Test conditions.....	11
8.3	Degree of severity: resistance to water – exposure to water (conditioning method 04).....	12
8.4	Recovery.....	12
8.5	Evaluation.....	12
<b>9</b>	<b>Adhesion test: pull-off test (conditioning method 05)</b> .....	<b>13</b>
9.1	General.....	13
9.2	Test conditions.....	13
9.3	Degree of severity: adhesion – pull-of test (conditioning method 05).....	14
9.4	Evaluation.....	14
<b>10</b>	<b>Environmental test code</b> .....	<b>14</b>

<b>Annex A (normative) Materials for abrasion testing of optical coatings</b> .....	<b>15</b>
<b>Annex B (informative) Cheesecloth pad, pad cover and fixture preparation for moderate abrasion testing of optical coatings</b> .....	<b>18</b>
<b>Annex C (normative) Visual examination of optical coatings</b> .....	<b>20</b>
<b>Bibliography</b> .....	<b>21</b>