

# ISO 23701:2023-04 (E)

## Optics and photonics - Laser and laser-related equipment - Photothermal technique for absorption measurement and mapping of optical laser components

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols used and units of measure .....	2
5	Test method .....	2
5.1	Test principle .....	2
5.1.1	General .....	2
5.1.2	Photothermal lensing (TL) .....	3
5.1.3	Photothermal deflection (PTD) .....	3
5.1.4	Rules for selecting reflected and transmitted photothermal detection schemes .....	3
5.2	Measurement arrangement and test equipment .....	3
5.2.1	Photothermal detection arrangement .....	3
5.2.2	Pump laser .....	6
5.2.3	Probe laser .....	6
5.2.4	Translation stage .....	6
5.2.5	Detection unit .....	7
5.2.6	Data acquisition and processing .....	7
5.2.7	Environment .....	7
5.3	Preparation of test sample .....	7
6	Test procedure .....	7
6.1	General .....	7
6.2	Measurements of photothermal amplitude and phase .....	8
6.3	Maps of photothermal amplitude and phase .....	8
6.4	Calibration of photothermal amplitude .....	9
6.5	Assessments of the measurement .....	10
7	Evaluation .....	11
7.1	Determination of absorption via photothermal measurement .....	11
7.2	Determination of absorptance via photothermal calibration .....	12
7.3	Two-dimensional/three-dimensional maps of absorption .....	13
7.4	Mapping area and spatial resolution .....	13
8	Test report .....	14
Annex A (informative) Theoretical and practical considerations on calibration .....		16
Annex B (informative) Separation of surface absorption and bulk absorption .....		18
Annex C (informative) Test report .....		21
Bibliography .....		22