

ISO 15004-2:2024-12 (E)

Ophthalmic instruments - Fundamental requirements and test methods - Part 2: Light hazard protection

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Classification principles	7
4.1	General	7
4.2	Group 1 instruments	9
4.3	Group 2 instruments	9
5	Requirements for classification	9
5.1	General	9
5.2	Requirements for classification as a Group 1 instrument	9
5.3	Requirements for classification as a Group 2 instrument	10
5.4	Exposure limits for Group 1 classification	10
5.4.1	Continuous wave instruments	10
5.4.2	Pulsed instruments	10
5.4.3	Time-limited instruments	11
5.4.4	Dose limited instruments	11
5.4.5	Scanning instruments	11
5.4.6	Instruments with multiple sources	12
5.4.7	Instruments for long-term repetitive daily use	12
5.5	Recommended maximum exposure (RME) values for Group 2 instruments	12
5.5.1	Continuous wave instruments	12
5.5.2	Pulsed instruments	12
5.5.3	Time-limited instruments	13
5.5.4	Scanning instruments	13
5.5.5	Instruments with multiple sources	13
5.5.6	Instruments for long-term repetitive daily use	14
5.6	Exposure limits and maximum recommended exposure values	14
6	Test methods	19
6.1	General	19
6.2	Classification of instruments into Group 1 or Group 2	19
6.3	Spectral measurements	20
6.4	Group 2 instruments: determination of time and number of pulses to reach recommended maximum exposure	20
6.4.1	Determination of time t_{\max} to reach the recommended maximum exposure for weighted corneal and lenticular ultraviolet radiation radiant exposure, H_{S-CL}	20
6.4.2	Determination of time t_{\max} to reach the recommended maximum exposure for photochemical aphakic retinal radiant exposure	20
6.4.3	Determination of the number of pulses necessary to reach the recommended maximum exposure for photochemical aphakic retinal exposure, n_{\max} (for pulsed instruments)	21
7	Information supplied by the manufacturer	21
7.1	Information provided on request	21
7.2	Accompanying documents	21
7.2.1	General	21
7.2.2	Dose-limited instruments	21

7.2.3	Cautionary statements.....	21
7.3	Marking.....	25
7.3.1	Radiation output.....	25
7.3.2	Consult accompanying documents.....	25
7.3.3	Safety information for optical radiation.....	25
Annex A (normative) Spectral weighting functions.....		26
Annex B (informative) Measurement instruments.....		33
Annex C (informative) Measurement methods for radiance/irradiance.....		37
Annex D (informative) Guidance on the direct measurement of irradiance.....		42
Annex E (informative) Examples of measurement methods for specific ophthalmic instruments.....		44
Annex F (informative) Safety signs.....		55
Bibliography.....		56