

ISO 23747:2007-07 (E)

Anaesthetic and respiratory equipment - Peak expiratory flow meters for the assessment of pulmonary function in spontaneously breathing humans

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	General requirements	2
4.1	Safety for PEFMs that utilize electricity	2
4.2	Mechanical safety for all PEFMs	2
5	Identification, marking and documents	2
5.1	Marking of the scale or display	2
5.2	Marking of PEFM or packaging	3
5.3	Instructions for use	3
5.4	Technical description	4
6	PEFM measurement range	4
7	Performance requirements	4
7.1	Error of measurement	4
7.2	Linearity	4
7.3	Resistance to flow	5
7.4	Frequency response	5
8	Dismantling and reassembly	5
9	Effects of mechanical ageing	5
10	Effects of dropping a hand-held PEFM	5
11	Cleaning, sterilization and disinfection	5
11.1	Re-usable PEFM and parts	5
11.2	PEFM and parts delivered sterile	6
12	Compatibility with substances	6
13	Biocompatibility	6
Annex A (informative) Rationale for tests and examples of test apparatus		7
Annex B (normative) Determination of error, repeatability and resistance to PEFM output		10
Annex C (normative) Determination of frequency response		13
Annex D (normative) Test methods for determination of the effects of dismantling, ageing and dropping		15
Annex E (informative) Environmental aspects		17
Annex F (informative) Reference to the essential principals		19
Bibliography		22