

# IEC 80601-2-71:2015-06 (E)

## Medical electrical equipment - Part 2-71: Particular requirements for the basic safety and essential performance of functional Near-Infrared Spectroscopy (NIRS) equipment

---

### CONTENTS

- FOREWORD..... 4
- INTRODUCTION..... 6
- 201.1 Scope, object and related standards..... 7
- 201.2 Normative references ..... 9
- 201.3 Terms and definitions ..... 9
- 201.4 General requirements..... 12
- 201.5 General requirements for testing ME EQUIPMENT..... 12
- 201.6 Classification of ME EQUIPMENT and ME SYSTEMS ..... 12
- 201.7 ME EQUIPMENT identification, marking and documents..... 12
- 201.8 Protection against electrical HAZARDS from ME EQUIPMENT ..... 12
- 201.9 Protection against mechanical HAZARDS of ME EQUIPMENT and ME SYSTEMS ..... 13
- 201.10 Protection against unwanted and excessive radiation HAZARDS ..... 13
- 201.11 Protection against excessive temperatures and other hazards..... 13
- 201.12 ACCURACY of controls and instruments and protection against hazardous outputs ..... 13
- 201.13 HAZARDOUS SITUATIONS and fault conditions for ME EQUIPMENT..... 21
- 201.14 PROGRAMMABLE ELECTRICAL MEDICAL SYSTEMS (PEMS) ..... 21
- 201.15 Construction of ME EQUIPMENT..... 21
- 201.16 ME SYSTEMS ..... 21
- 201.17 Electromagnetic compatibility of ME EQUIPMENT and ME SYSTEMS ..... 21
- Annexes ..... 22
- Annex C (informative) Guide to marking and labelling requirements for ME EQUIPMENT and ME SYSTEMS..... 22
- Annex AA (informative) Particular guidance and rationale ..... 23
- Annex BB (normative) Evaluating ME EQUIPMENT performance using the FUNCTIONAL NIRS PHANTOM ..... 25
- Annex CC (informative) Reference to the essential principles ..... 34
- Bibliography ..... 36
- Index of defined terms ..... 37

Figure 201.101 – FULL WIDTH AT HALF MAXIMUM of spectral power distribution .....	10
Figure 201.102 – Measurement of AVERAGE OPTICAL POWER .....	14
Figure 201.103 – Measurement of PEAK WAVELENGTH and FWHM .....	15
Figure 201.104 – Measurement of signal stability .....	16
Figure 201.105 – Measurement of RESPONSE TIME.....	17
Figure 201.106 – Rise time and fall time in RESPONSE TIME.....	18
Figure 201.107 – Measurement of signal-to-noise ratio .....	19
Figure 201.108 – Measurement of SIGNAL CROSS-TALK.....	21
Figure 201.BB.1 – The FUNCTIONAL NIRS PHANTOM in two states with different detected light intensities .....	28
Figure BB.2 – FUNCTIONAL NIRS PHANTOM measurement using the reference system .....	29
Figure BB.3 – FUNCTIONAL NIRS PHANTOM measurement using the ME EQUIPMENT to be evaluated .....	29
Figure BB.4 – Schematic for measurement of OPTICAL LOSS .....	32
Table 201.101 – Performance tests employing the FUNCTIONAL NIRS PHANTOM or attenuator and the required OPTICAL LOSS .....	13
Table 201.C.101 – Marking on the outside of FUNCTIONAL NIRS EQUIPMENT or their parts.....	22
Table 201.C.102 – ACCOMPANYING DOCUMENTS, instructions for use of FUNCTIONAL NIRS EQUIPMENT .....	22
Table CC.1 – Correspondence between this particular standard and the essential principles.....	34