

ISO 11137-3:2017-06 (E)

Sterilization of health care products - Radiation - Part 3: Guidance on dosimetric aspects of development, validation and routine control

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	1
3.1	General	1
3.2	Symbols	3
4	Measurement of dose	4
4.1	General	4
4.1.1	Direct and indirect dose measurements	4
4.1.2	Dosimetry systems	4
4.1.3	Best estimate of dose	4
4.2	Dosimetry system selection and calibration	5
4.2.1	General	5
4.2.2	Selection of dosimetry systems	5
4.2.3	Calibration of dosimetry systems	5
4.3	Dose measurement uncertainty	6
4.3.1	General concepts	6
4.3.2	The Guide to the expression of uncertainty in measurement (GUM) methodology	6
4.3.3	Radiation sterilization specific aspects of dose measurement uncertainty	7
5	Establishing the maximum acceptable dose	8
6	Establishing the sterilization dose	9
7	Installation qualification	10
8	Operational qualification	11
8.1	General	11
8.2	Gamma irradiators	11
8.3	Electron beam irradiators	13
8.4	X-ray irradiators	15
9	Performance qualification	17
9.1	General	17
9.2	Gamma irradiators	18
9.2.1	Loading pattern	18
9.2.2	Dosimetry	19
9.2.3	Analysis of dose mapping data	20
9.3	Electron beam irradiators	20
9.3.1	Loading pattern	20
9.3.2	Dosimetry	22
9.3.3	Analysis of dose mapping data	23
9.4	X-ray irradiators	23
9.4.1	Loading pattern	23
9.4.2	Dosimetry	24

9.4.3	Analysis of dose mapping data	25
10	Routine monitoring and control	25
10.1	General	25
10.2	Frequency of dose measurements	26
	Annex A (informative) Mathematical modelling	27
	Annex B (informative) Tables of references for dosimetry-related testing during IQ/OQ/PQ	30
	Annex C (informative) Tolerances associated with doses used in sterilization dose setting/ substantiation in ISO 11137-2 and ISO/TS 13004	33
	Annex D (informative) Application of dose measurement uncertainty in setting process target doses	34
	Bibliography	40