

# ISO 22716:2007-11 (E)

## Cosmetics - Good Manufacturing Practices (GMP) - Guidelines on Good Manufacturing Practices

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	<b>Scope .....</b>	<b>1</b>
2	<b>Terms and definitions .....</b>	<b>1</b>
3	<b>Personnel .....</b>	<b>4</b>
4	<b>Premises .....</b>	<b>6</b>
5	<b>Equipment .....</b>	<b>8</b>
6	<b>Raw materials and packaging materials .....</b>	<b>10</b>
7	<b>Production .....</b>	<b>11</b>
8	<b>Finished products .....</b>	<b>14</b>
9	<b>Quality control laboratory .....</b>	<b>15</b>
10	<b>Treatment of product that is out of specification .....</b>	<b>17</b>
11	<b>Wastes .....</b>	<b>17</b>
12	<b>Subcontracting .....</b>	<b>18</b>
13	<b>Deviations .....</b>	<b>19</b>
14	<b>Complaints and recalls .....</b>	<b>19</b>
15	<b>Change control .....</b>	<b>19</b>
16	<b>Internal audit .....</b>	<b>20</b>
17	<b>Documentation .....</b>	<b>20</b>