

# DIN EN 16965:2018-03 (E)

## Fertilizers - Determination of cobalt, copper, iron, manganese and zinc using flame atomic absorption spectrometry (FAAS)

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Principle .....	5
5	Interferences .....	5
6	Reagents .....	6
7	Apparatus .....	7
8	Procedure .....	7
8.1	Preparation of test and blank solutions .....	7
8.2	Preparation of the calibration solutions .....	7
8.3	Measurement .....	7
9	Calculation and expression of the results .....	8
10	Precision .....	8
10.1	Inter-laboratory test .....	8
10.2	Repeatability .....	9
10.3	Reproducibility .....	9
11	Test report .....	11
Annex A (informative) Statistical results of the inter-laboratory test .....		12
Bibliography .....		22