

ISO 5738:2004-09 (E)

Milk and milk products - Determination of copper content - Photometric method (Reference method)

Contents		Page
Foreword		iv
Foreword		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Reagents	2
6	Apparatus	3
7	Sampling	4
8	Procedure	4
8.1	Preparation of test sample	4
8.2	Weighing and pretreatment of the test portion	6
8.3	Digestion	7
8.4	Colour development	7
8.5	Blank test	8
8.6	Photometric measurements	8
8.7	Number of determinations	8
8.8	Calibration curve	8
9	Calculation and expression of results	8
9.1	Calculation	8
9.2	Expression of results	9
10	Precision	9
10.1	Interlaboratory test	9
10.2	Repeatability	9
10.3	Reproducibility	9
11	Test report	9
Annex A (informative) Results of interlaboratory test		10
Bibliography		11