

# ISO 16063-34:2019-12 (E)

## Methods for the calibration of vibration and shock transducers - Part 34: Testing of sensitivity at fixed temperatures

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Uncertainty of measurement .....	2
5	Ambient conditions .....	3
6	Apparatus .....	3
7	Method 1: Determination of complex sensitivity using a laser interferometer .....	4
7.1	General .....	4
7.2	Method .....	5
7.2.1	Test procedure .....	5
7.2.2	Expression of results .....	5
8	Method 2: Determination of complex sensitivity using a reference transducer inside a temperature chamber .....	6
8.1	General .....	6
8.2	Method .....	6
8.2.1	Test procedure .....	6
8.2.2	Expression of results .....	7
9	Method 3: Determination of complex sensitivity using a reference transducer outside the temperature chamber .....	7
9.1	General .....	7
9.2	Method .....	8
9.2.1	Test procedure .....	8
9.2.2	Expression of results .....	9
10	Preferred amplitudes, frequencies and temperatures .....	9
11	Test report .....	10
Annex A (informative)	Determination of the achieving time of setpoint temperature for a device under test .....	12
Annex B (informative)	Evaluating uncertainty caused by temperature tolerance .....	14
Bibliography .....		16