

ISO 16063-12:2002-04 (E)

Methods for the calibration of vibration and shock transducers - Part 12: Primary vibration calibration by the reciprocity method

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Uncertainty of measurement	1
4	Symbols	1
5	Requirements for apparatus	2
6	Ambient conditions	4
7	Preferred amplitudes and frequencies	4
8	Procedure	4
9	Computation of sensitivity	6
Annex A (normative) Calculation of uncertainty		10
Annex B (informative) Application of the theory of reciprocity to the calibration of electromechanical transducers		14
Bibliography		20