DIN EN 12077-2:2008-12 (E)

Cranes safety - Requirements for health and safety - Part 2: Limiting and indicating devices (includes Amendment A1:2008)

Conte	ents	Page
Forewor	rd	3
Introduc	tion	4
1	Scope	5
2	Normative references	5
3	Definitions	5
4	List of significant hazards	7
Table 1	List of significant hazards and associated requirements	8
Table 1	List of significant hazards and associated requirements (Concluded)	9
5 5.1	Safety requirements and/or measures	
5.1 5.2	Limiters and indicators	
5.3	Rated capacity limiters and indicators - General requirements	
5.4	Rated capacity limiters - Specific requirements	
5.5	Rated capacity indicators - Specific requirements	
5.6	Motion and performance limiters	
5.7	Indicators	
6	Verification of the safety requirements and/or measures	15
Table 2	Methods to be used to verify conformity with the safety requirements and/or measure	d16
Table 2	Methods to be used to verify conformity with the safety requirements and/or measure (Concluded)	
7	Information for use	18
7.1	Instructions shall be provided for the protection of limiters and indicators when arc welding is carried out on the crane	18
7.2	Instructions shall be provided for the actions to be taken to protect the limiter/indicat when overload testing the crane	or
7.3	Warnings shall be provided to prevent excessive paint from being applied to critical areas	
Annex Z	A (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC	19
Annex Z	B (informative) !!!!Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC	20