

# DIN EN 13042-3:2010-05 (E)

## Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 3: IS machines (includes Amendment A1:2009)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	6
3	Terms and definitions .....	7
4	List of significant hazards .....	7
5	Safety requirements and/or protective measures .....	9
5.1	General .....	9
5.2	Starting and stopping and unexpected start-up .....	10
5.3	Emergency-stop equipment .....	10
5.4	Prevention of unexpected movements of individual mechanisms .....	10
5.5	Walking surfaces .....	11
5.6	Operation of manual controls .....	11
5.7	Removal of broken glass .....	11
5.8	Noise .....	11
5.9	Guards .....	12
5.10	Heat-protective equipment .....	12
5.11	Gob distributor and interceptor .....	12
5.12	Gob distributor operation .....	12
5.13	Necessary movements in case of power failure .....	13
5.14	Electrical equipment .....	13
5.15	Pneumatic system .....	13
5.16	Energy supply disconnecting devices .....	13
6	Verification of safety requirements and/or protective measures .....	13
7	Information for use .....	14
7.1	General .....	14
7.2	Accompanying documents (in particular: instruction handbook) .....	14
7.3	Marking .....	15
Annex A (informative) Glossary .....		16
Annex B (informative) Blow and blow process .....		17
Annex C (informative) Press and blow process .....		18
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC .....		19
Annex ZB (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC" .....		20
Bibliography .....		21

<b>Tables Table 1 -- List of significant hazards .....</b>	<b>8</b>
<b>Table 2 -- Individual testing for requirements stated in Clause 5 .....</b>	<b>13</b>