

# ISO 27894:2009-12 (E)

## Vacuum technology - Vacuum gauges - Specifications for hot cathode ionization gauges

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	<b>Scope .....</b>	<b>1</b>
2	<b>Normative references .....</b>	<b>1</b>
3	<b>Terms and definitions .....</b>	<b>2</b>
4	<b>Symbols and abbreviated terms .....</b>	<b>6</b>
5	<b>Principle of hot cathode ionization gauge .....</b>	<b>7</b>
6	<b>Specifications for hot cathode ionization gauge to be provided by manufacturers .....</b>	<b>7</b>
7	<b>Additional (optional) specifications for hot cathode ionization gauge to be provided by manufacturers .....</b>	<b>10</b>
8	<b>Influences contributing to the measurement uncertainty with hot cathode ionization gauges .....</b>	<b>11</b>
	<b>Annex A (informative) Typical Bayard-Alpert gauge with a glass envelope .....</b>	<b>14</b>
	<b>Annex B (informative) Typical electrical connection of a Bayard-Alpert gauge .....</b>	<b>15</b>
	<b>Annex C (informative) Problems with ionization gauges .....</b>	<b>16</b>
	<b>Bibliography .....</b>	<b>18</b>