

DIN EN 14658:2010-06 (E)

Continuous handling equipment and systems - General safety requirements for continuous handling equipment for opencast lignite mining (includes Amendment A1:2010)

Contents

Page

Foreword.....	4
Introduction	5
1 Scope	6
2 Normative references	6
3 Terms and definitions	7
4 List of significant hazards	9
4.1 General.....	9
4.2 Mechanical hazards	9
4.2.1 Crushing and shearing.....	9
4.2.2 Entanglement, drawing-in and trapping.....	9
4.2.3 Stability	9
4.2.4 Hazards generated by fracturing and rupturing during operation	10
4.2.5 Hazards generated by slipping, tripping and falling	10
4.3 Electrical equipment hazards	10
4.4 Thermal hazards	10
4.5 Radiation hazards	10
4.6 Hazards due to handled materials	10
4.7 Hazards due to neglect of ergonomic principles	10
4.8 Hazards due to energy supply failure.....	11
4.9 Combination of hazards	11
5 Safety requirements and/or measures	11
5.1 General.....	11
5.2 Mechanical hazards	11
5.2.1 Crushing and shearing hazards	11
5.2.2 Entanglement, drawing-in and trapping.....	12
5.2.3 Stability	12
5.2.4 Hazards generated by fracturing and rupturing during operation	12
5.2.5 Access	12
5.3 Electrical equipment requirements.....	14
5.3.1 General.....	14
5.3.2 Start-up	14
5.3.3 Stopping, restarting after actuation of the stop device	14
5.3.4 Unexpected or unintended start-up	15
5.4 Thermal hazards	16
5.5 Radiation hazards	16
5.6 Hazards due to handled materials	16
5.7 Hazards due to neglect of ergonomic principles	16
5.8 Hazards due to energy supply failure.....	17
5.9 Combination of hazards	17
6 Verification of compliance with safety requirements and/or measures	17
6.1 General.....	17
6.2 Documents demonstrating compliance at the design/manufacturing stages	17
6.3 Verification at the place of installation	17
7 Information for use	20
7.1 General.....	20
7.2 Signals and warning devices.....	20
7.3 Accompanying documentation (operating instruction handbook)	20
7.3.1 General.....	20

7.3.2	Information on the continuous handling equipment	20
7.3.3	Instructions for the use of the continuous handling equipment.....	21
7.3.4	Instructions for maintenance	22
7.4	Marking	22
Annex A (normative)	List of hazards according to EN 1050 and reference to the corresponding safety requirements to be met by continuous handling equipment in opencast lignite mining	23
Annex ZA (informative)	Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC amended by 98/79/EC ^{A1}	28
Annex ZB (informative)	Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC ^{A1}	30