

ISO 11614:1999-09 (E)

Reciprocating internal combustion compression-ignition engines - Apparatus for measurement of the opacity and for determination of the light absorption coefficient of exhaust gas

Contents	Page
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
4 Symbols and units	2
5 Principles of opacimeters	4
5.1 General	4
5.2 Measurement of light absorption coefficient	4
5.3 Conditions of use	4
6 Specifications of opacimeters for measurement of opacity)	4
6.1 Basic specifications	4
6.2 Design specifications	5
7 Additional specifications for opacimeters to measure light absorption coefficient	6
7.1 Reference conditions	6
7.2 Basic specifications	7
7.3 Design specifications	7
8 Measurement of transients	9
8.1 General	9
8.2 Response of the opacimeter	10
8.3 Physical delay time,	12
8.4 Temperature response time, t_j	12
8.5 Peak hold	12
9 Specifications concerning specific opacimeters and their installation	13
9.1 Sampling opacimeter	13
9.2 In-line full-flow opacimeter	13
9.3 End of line (plume-type) opacimeter	14
9.4 Opacimeter for free-acceleration tests	14
9.5 Installation of opacimeters in a test bench	15
10 Data and instrumentation requirements	16
10.1 Example of specific requirements for sampling opacimeters	16
10.2 Data requirements	17
10.3 Instrumentation requirements	18
11 Verification of opacimeter types	19
11.1 Introduction	19
11.2 General considerations	19

11.3	Data supplied by the manufacturer.....	19
11.4	Instrumentation requirements.....	19
11.5	Instrument verification.....	19
11.6	Verification of basic and design specifications.....	21
11.7	Verification of response characteristics.....	32
12	Verification of in-service conformity of opacimeters.....	36
12.1	General.....	36
12.2	Items to be checked.....	36
12.3	Details of checks.....	36
13	Test report of opacimeter verification.....	37
13.1	Data and instrumentation requirements.....	37
13.2	Results of instrument verification.....	37
13.3	Results of verification of basic and design specifications (see 11.6).....	39
13.4	Verification of response characteristics (see 11.7).....	47
Annex A (normative) Determination of the "mean exhaust gas temperature" in the smoke chamber of an air-scavanged opacimeter.....		54
Bibliography.....		57

