

DIN EN ISO 19085-6:2018-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines ("toupies") (ISO 19085-6:2017)

Contents		Page
European foreword		5
Annex ZA (informative) Relationship between this European Standard and the essential requirements of Directive 2006/42/EC		6
Foreword		9
Introduction		10
1	Scope	11
2	Normative references	12
3	Terms and definitions	12
4	List of significant hazards	18
5	Safety requirements and measures for controls	20
5.1	Safety and reliability of control systems.....	20
5.2	Control devices.....	20
5.3	Start.....	21
5.4	Safe stops.....	21
5.4.1	General.....	21
5.4.2	Normal stop.....	21
5.4.3	Operational stop.....	21
5.4.4	Emergency stop.....	21
5.5	Braking function of tool spindles.....	22
5.6	Mode selection.....	22
5.7	Spindle speed changing.....	22
5.7.1	Spindle speed changing by changing belts on the pulleys.....	22
5.7.2	Spindle speed changing by incremental speed change motor.....	22
5.7.3	Infinitely variable speed by frequency inverter.....	22
5.7.4	Spindle speed limiting device for tenoning.....	22
5.7.5	Changing of the direction of spindle rotation.....	22
5.8	Failure of any power supply.....	23
5.9	Manual reset control.....	23
5.10	Enabling control.....	23
5.11	Machine moving parts speed monitoring.....	23
5.12	Time delay.....	24
5.13	Power driven adjustment of arbor, demountable power feed unit, fences and table insert.....	24
6	Safety requirements and measures for protection against mechanical hazards	24
6.1	Stability.....	24
6.1.1	Stationary machines.....	24
6.1.2	Displaceable machines.....	24
6.2	Risk of break-up during operation.....	25
6.3	Tool holder and tool design.....	25
6.3.1	General.....	25
6.3.2	Spindle locking.....	27
6.3.3	Circular saw blade fixing device.....	28
6.3.4	Flange dimension for circular saw blades.....	28
6.3.5	Arbor rings.....	28
6.3.6	Quick tool/arbor change system.....	28
6.3.7	Manual adjustment of arbor height.....	28
6.3.8	Manual adjustment of arbor inclination.....	29

6.4	Braking.....	29
6.4.1	Braking of tool spindles.....	29
6.4.2	Maximum run-down time.....	29
6.4.3	Brake release.....	30
6.5	Safeguards.....	30
6.5.1	Fixed guards.....	30
6.5.2	Interlocking movable guards.....	30
6.5.3	Hold-to-run control.....	30
6.5.4	Two-hand control.....	30
6.5.5	Electro-sensitive protective equipment (ESPE).....	30
6.5.6	Pressure-sensitive protective equipment (PSPE).....	30
6.6	Prevention of access to moving parts.....	30
6.6.1	General.....	30
6.6.2	Guarding of tools.....	30
6.6.3	Guarding of drives.....	34
6.6.4	Guarding of shearing and/or crushing zones.....	34
6.7	Impact hazard.....	34
6.8	Clamping devices.....	34
6.9	Measures against ejection.....	35
6.9.1	General.....	35
6.9.2	Guards materials and characteristics.....	35
6.9.3	Anti-kickback devices.....	35
6.10	Work-piece supports and guides.....	37
6.10.1	Table.....	37
6.10.2	Work-piece guiding for straight work.....	40
6.10.3	Work-piece guiding for curved work.....	40
6.11	Safety appliances.....	41
7	Safety requirements and measures for protection against other hazards.....	42
7.1	Fire.....	42
7.2	Noise.....	42
7.2.1	Noise reduction at the design stage.....	42
7.2.2	Noise emission measurement.....	42
7.3	Emission of chips and dust.....	42
7.4	Electricity.....	43
7.4.1	General.....	43
7.4.2	Displaceable machines.....	43
7.5	Ergonomics and handling.....	43
7.6	Lighting.....	43
7.7	Pneumatics.....	43
7.8	Hydraulics.....	43
7.9	Electromagnetic compatibility.....	43
7.10	Laser.....	44
7.11	Static electricity.....	44
7.12	Errors of fitting.....	44
7.13	Isolation.....	44
7.14	Maintenance.....	44
8	Information for use.....	44
8.1	Warning devices.....	44
8.2	Marking.....	44
8.2.1	General.....	44
8.2.2	Additional markings.....	44
8.3	Instruction handbook.....	44
8.3.1	General.....	44
8.3.2	Additional information.....	44
	Annex A (informative) Performance level required.....	48
	Annex B (normative) Test for braking function.....	50
	Annex C (normative) Stability test for displaceable machines.....	51

Annex D (normative) Impact test for guards	52
Annex E (normative) Noise emission measurement for machines not in ISO 7960:1995	53
Annex F (informative) Determination of maximum spindle speeds for single piece arbors	54
Annex G (normative) Rigidity test for pressure pads, hand protectors and guiding steadies	58
Bibliography	63