

# DIN 5481:2019-04 (E)

## Serration splines

---

### Contents

Page

Foreword .....	4
1 Scope .....	6
2 Normative references .....	6
3 Symbols and abbreviated terms.....	6
4 Structure .....	7
5 Diameters .....	8
5.1 General .....	8
5.2 Hub diameters .....	9
5.3 Shaft diameters .....	10
6 Fit system for tooth thickness/space width.....	10
6.1 Fit diagram .....	10
6.2 Structure of the tolerance system .....	11
6.3 Total tolerance.....	11
6.4 Actual tolerance $T_{act}$ .....	11
6.5 Effective tolerance $T_{eff}$ .....	11
6.6 Space widths and dimensions of hubs .....	12
6.7 Tooth thicknesses and dimensions of shafts .....	14
6.7.1 Tooth thicknesses and dimensions of shafts with straight flanks.....	14
6.7.2 Tooth thicknesses and dimensions of shafts with involute flanks.....	16
7 Guideline values for individual deviations .....	18
7.1 General .....	18
7.2 Guideline values for individual deviations of hubs.....	18
7.3 Guideline values for individual deviations of shafts .....	19
7.4 Reference values for radial runout.....	20
8 Designation.....	20
9 Data to be shown on drawings.....	20
10 Quality characteristics.....	21
11 Gauges/general .....	22
11.1 Types of gauge and gauge dimensions.....	22
11.1.1 Composite GO gauges .....	22
11.1.2 Sector NO GO gauges.....	22
11.1.3 Plug gauges .....	22
11.1.4 Ring gauges .....	23
11.2 Materials, surface finishes, reference temperature, insertion force for inspection.....	24
11.3 Calculating gauge dimensions.....	25
11.3.1 Tolerance diagram .....	25
11.3.2 Determining measurements over/between pins .....	25
11.3.3 Individual deviations and positional deviations.....	25
11.4 Gauges for hubs .....	27
11.4.1 GO plug gauges.....	27
11.4.2 NO GO plug gauges.....	29

<b>11.5</b>	<b>Gauges for shafts.....</b>	<b>31</b>
<b>11.5.1</b>	<b>GO ring gauges.....</b>	<b>31</b>
<b>11.5.2</b>	<b>NO GO ring gauges, “precision fit” .....</b>	<b>33</b>
<b>11.5.3</b>	<b>NO GO ring gauges, “rough fit” .....</b>	<b>35</b>
<b>11.6</b>	<b>Inspecting gauges.....</b>	<b>36</b>
<b>11.6.1</b>	<b>Inspection of gauges in new condition .....</b>	<b>36</b>
<b>11.6.2</b>	<b>Gauge wear inspection .....</b>	<b>37</b>
<b>11.6.3</b>	<b>Master ring gauges.....</b>	<b>38</b>
<b>11.7</b>	<b>Marking.....</b>	<b>38</b>
<b>11.8</b>	<b>Data to be shown on drawings.....</b>	<b>38</b>
	<b>Bibliography.....</b>	<b>40</b>