

ISO 16890-2:2022-07 (E)

Air filters for general ventilation - Part 2: Measurement of fractional efficiency and air flow resistance

Contents		Page
Foreword		vi
Introduction		viii
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
3.1	Air flow and resistance	2
3.2	Test device	2
3.3	Aerosol	2
3.4	Particle counter	3
3.5	Efficiency	3
3.6	Other terms	4
4	Symbols and abbreviated terms	4
4.1	Symbols	4
4.2	Abbreviated terms	6
5	General test requirements	6
5.1	Test device requirements	6
5.2	Test device installation	6
5.3	Test rig requirements	7
6	Test materials	7
6.1	Liquid phase aerosol	7
6.1.1	DiEthylHexylSebacate (DEHS) test aerosol	7
6.1.2	DEHS properties	7
6.1.3	Liquid phase aerosol generation	7
6.2	Solid phase aerosol	8
6.2.1	Potassium chloride (KCl) test aerosol	8
6.2.2	KCl properties	8
6.2.3	Solid phase aerosol generation	9
6.3	Reference aerosols	10
6.3.1	Reference aerosol for 0,3 µm to 1,0 µm	10
6.3.2	Reference aerosol for 1,0 µm to 10,0 µm	10
6.4	Aerosol loading	10
7	Test equipment	11
7.1	Test rig	11
7.1.1	Dimensions	11
7.1.2	Construction materials	11
7.1.3	Test rig shape	12
7.1.4	Test rig air supply	12
7.1.5	Test rig isolation	12
7.1.6	D/S mixing orifice	12
7.1.7	Aerosol sampling	13
7.1.8	Test rig air flow rate measurement	15
7.1.9	Resistance to air flow measurement	15
7.1.10	Test devices not measuring 610 mm × 610 mm (24.0 inches × 24.0 inches)	16

7.1.11	Dust injection testing	16
7.2	Aerosol particle counter	17
7.2.1	General	17
7.2.2	OPC sampled size range	17
7.2.3	OPC particle size ranges	17
7.2.4	Sizing resolution	18
7.2.5	Calibration	18
7.2.6	Air flow rate	18
7.2.7	Zero counting	18
7.2.8	Dual OPC(s)	18
7.3	Temperature, relative humidity	18
8	Qualification of test rig and apparatus	19
8.1	Schedule of qualification testing requirements	19
8.1.1	General	19
8.1.2	Qualification testing	19
8.1.3	Qualification documentation	19
8.2	Qualification testing	20
8.2.1	Test rig -- Pressure system testing	20
8.2.2	OPC -- Air flow rate stability test	21
8.2.3	OPC -- Zero test	21
8.2.4	OPC -- Sizing accuracy	21
8.2.5	OPC -- Overload test	22
8.2.6	Aerosol generator -- Response time	22
8.2.7	Aerosol generator -- Neutralizer	23
8.2.8	Test rig -- Air leakage test	24
8.2.9	Test rig -- Air velocity uniformity	24
8.2.10	Test rig -- Aerosol uniformity	25
8.2.11	Test rig -- Downstream mixing	26
8.2.12	Test rig -- Empty test device section pressure	28
8.2.13	Test rig -- 100 % efficiency test and purge time	28
8.2.14	Test rig -- Correlation ratio	29
8.3	Maintenance	29
8.3.1	General	29
8.3.2	Test rig -- Background counts	30
8.3.3	Test rig -- Reference filter test	30
8.3.4	Test rig -- Pressure reference test	31
8.3.5	Test rig -- Final filter resistance	32
9	Test methods	32
9.1	Air flow rate	32
9.2	Measurement of resistance to air flow	32
9.3	Measurement of fractional efficiency	32
9.3.1	Aerosol sampling protocol	32
9.3.2	Background sampling	32
9.3.3	Testing sequence for a single OPC	33
9.3.4	Testing sequence for dual OPC	37
10	Data reduction and calculations	38
10.1	Correlation ratio	38
10.1.1	Correlation ratio general	38
10.1.2	Correlation ratio data reduction	39
10.2	Penetration and fractional efficiency	40
10.2.1	Penetration and fractional efficiency general	40
10.2.2	Penetration data reduction	41
10.3	Data quality requirements	43
10.3.1	Correlation background counts	43
10.3.2	Efficiency background counts	43
10.3.3	Correlation ratio	43
10.3.4	Penetration	44
10.4	Fractional efficiency calculation	45

11	Reporting results	45
11.1	General	45
11.2	Required reporting elements	45
11.2.1	Report general	45
11.2.2	Report values	45
11.2.3	Report summary	46
11.2.4	Report details	47
Annex A (informative) Example		50
Annex B (informative) Resistance to air flow calculation		57
Bibliography		59