

# DIN EN ISO 23582-1:2023-08 (E)

## Plastics and rubber machines - Clamping systems - Part 1: Safety requirements for magnetic clamping systems (ISO 23582-1:2023)

---

<b>Contents</b>	<b>Page</b>
<b>European foreword</b> .....	<b>3</b>
<b>Foreword</b> .....	<b>4</b>
<b>Introduction</b> .....	<b>5</b>
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Safety requirements and/or protective/risk reduction measures</b> .....	<b>8</b>
4.1 General .....	8
4.2 Magnets .....	8
4.3 Magnetic plate(s) .....	8
4.4 Magnetizing/demagnetizing current .....	8
4.5 Magnetic clamping control system .....	8
4.5.1 Magnetic clamping control system detection requirements .....	8
4.5.2 Magnetic clamping control system magnetizing/demagnetizing .....	8
4.5.3 Magnetic clamping control system enabling machine movements .....	9
4.6 Magnetic clamping system force .....	9
4.6.1 General .....	9
4.6.2 Magnetic clamping system force when the MCS is integrated in horizontal machines .....	9
4.6.3 Magnetic clamping system force when the MCS is integrated in vertical machines .....	9
4.7 Electrical hazards and hazards due to electromagnetic interference .....	10
4.7.1 General .....	10
4.7.2 Basic protection .....	10
4.7.3 Fault protection .....	10
4.7.4 Protection against ingress of solids and liquids .....	10
4.7.5 Protection against electromagnetic interference .....	10
<b>5 Verification of safety requirements and/or protective/risk reduction measures</b> .....	<b>10</b>
<b>6 Information for the integration and the use of the MCS</b> .....	<b>11</b>
6.1 Instruction for the integration of the MCS in a plastics and rubber machine .....	11
6.1.1 General .....	11
6.1.2 Forces acting against the magnetic clamping system force .....	11
6.1.3 Machine movements .....	11
6.1.4 Signals from the machine to the MCS .....	11
6.2 Instruction for the use of an MCS in a plastics and rubber machine .....	12
<b>7 Marking</b> .....	<b>13</b>
<b>Annex A (informative) List of significant hazards</b> .....	<b>14</b>
<b>Annex B (informative) Cantilever effect for half mould in horizontal machine</b> .....	<b>16</b>