

# DIN EN ISO 23062:2024-06 (E)

## Foundry machinery - Safety requirements for molding and coremaking machinery and associated equipment (ISO 23062:2022)

---

<b>Contents</b>		<b>Page</b>
<b>European foreword</b> .....		<b>4</b>
<b>Annex ZA (informative) Relationship between this European Standard and the essential requirements of EU Directive 2006/42/EC aimed to be covered</b> .....		<b>5</b>
<b>Foreword</b> .....		<b>7</b>
<b>Introduction</b> .....		<b>8</b>
<b>1</b>	<b>Scope</b> .....	<b>9</b>
<b>2</b>	<b>Normative references</b> .....	<b>9</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>10</b>
<b>4</b>	<b>Significant hazards and risk assessment</b> .....	<b>14</b>
4.1	General .....	14
4.2	Interfaces to the linked/integrated equipment .....	15
<b>5</b>	<b>Safety requirements and/or protective/risk reduction measures</b> .....	<b>15</b>
5.1	General .....	15
5.1.1	Fixed guards .....	15
5.1.2	Movable guards .....	15
5.1.3	Electro-sensitive protective devices (ESPD) .....	16
5.1.4	Several persons at the same time being present at hazardous zones .....	16
5.1.5	Control systems .....	16
5.1.6	Electrical equipment .....	17
5.1.7	Safety-related control systems .....	17
5.1.8	Safety-related software and parameters .....	17
5.1.9	Remote access to the control systems .....	18
5.1.10	Two-hand control devices .....	18
5.1.11	Ergonomics .....	18
5.1.12	Noise .....	19
5.1.13	Vibrations .....	20
5.1.14	Surface temperatures and heat radiation .....	20
5.1.15	Safety signs and warning devices .....	20
5.1.16	Exhaust systems .....	21
5.1.17	Fire and explosion protection .....	21
5.1.18	Fluid systems .....	21
5.1.19	Mechanical stability .....	21
5.2	Significant hazards, hazardous situations, safety requirements and/or protective/risk reduction measures .....	21
5.3	Significant hazards, hazardous situations, safety requirements and/or protective/risk reduction measures: General requirements .....	22
5.4	Significant hazards, hazardous situations, safety requirements and/or protective/risk reduction measures: Sand conditioning and reclamation equipment .....	24
5.5	Significant hazards, hazardous situations, safety requirements and/or protective/risk reduction measures: Molding machinery and plants .....	24
5.6	Significant hazards, hazardous situations, safety requirements and/or protective/risk reduction measures: Coremaking machinery and coremaking lines .....	36
5.7	Significant hazards, hazardous situations, safety requirements and/or protective/risk reduction measures: Knock-out equipment .....	39
<b>6</b>	<b>Verification of the safety requirements and/or preventative measures</b> .....	<b>40</b>
6.1	General .....	40
6.2	Safety systems .....	40

6.3	Electrical safety.....	41
6.4	Pressure release of dust and gas explosions.....	41
6.5	Explosiveness of dust or gaseous substances.....	41
6.6	Stress analysis.....	41
6.7	Airborne substances generated during operation.....	41
6.8	Noise.....	41
6.9	Verification in accordance with Vibration.....	41
6.10	Safety marking.....	41
<b>7</b>	<b>Information for use.....</b>	<b>41</b>
7.1	General.....	41
7.2	Warning devices and safety signs.....	42
7.3	Minimum marking.....	42
7.4	Accompanying documents.....	42
	7.4.1 Instruction handbook.....	42
	7.4.2 Operation manual.....	42
	7.4.3 Maintenance manual.....	44
7.5	Training of personnel.....	44
<b>8</b>	<b>Supplementary information regarding repair work.....</b>	<b>44</b>
	<b>Annex A (normative) Preventing hazards from hydraulic and pneumatic equipment as well as electrically driven equipment.....</b>	<b>46</b>
	<b>Annex B (informative) Main components of hazardous gases, fumes and dusts during core and mold making.....</b>	<b>49</b>
	<b>Bibliography.....</b>	<b>51</b>