

ISO 19085-6:2024-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines (toupie)

| Contents | | Page |
|---------------------|--|-------------|
| Foreword | | vi |
| Introduction | | vii |
| 1 | Scope | 1 |
| 2 | Normative references | 2 |
| 3 | Terms and definitions | 2 |
| 4 | Safety requirements and measures for controls | 9 |
| 4.1 | Safety and reliability of control systems | 9 |
| 4.2 | Control devices | 9 |
| 4.3 | Start | 10 |
| 4.3.1 | Direct start | 10 |
| 4.3.2 | Start via control power-on | 10 |
| 4.4 | Safe stops | 11 |
| 4.4.1 | General | 11 |
| 4.4.2 | Normal stop | 11 |
| 4.4.3 | Operational stop | 11 |
| 4.4.4 | Emergency stop | 11 |
| 4.5 | Braking function of tools | 11 |
| 4.6 | Mode selection | 11 |
| 4.7 | Tool speed changing | 11 |
| 4.7.1 | Speed changing by shifting the belts on the pulleys | 11 |
| 4.7.2 | Speed changing by incremental speed change motor | 11 |
| 4.7.3 | Infinitely variable speed by frequency inverter | 11 |
| 4.7.4 | Speed limiting device for tenoning | 11 |
| 4.7.5 | Changing the direction of tool rotation | 12 |
| 4.8 | Failure of any power supply | 12 |
| 4.9 | Manual reset control | 13 |
| 4.10 | Standstill detection and monitoring | 13 |
| 4.11 | Machine moving parts speed monitoring | 13 |
| 4.12 | Time delay | 13 |
| 4.13 | Teleservice | 13 |
| 4.14 | Power-driven adjustment of arbor, demountable power feed unit, fences and table insert | 13 |
| 5 | Safety requirements and measures for protection against mechanical hazards | 14 |
| 5.1 | Stability | 14 |
| 5.2 | Risk of break-up during operation | 14 |
| 5.3 | Tool and tool fixing design | 14 |
| 5.3.1 | General | 14 |
| 5.3.2 | Spindle locking | 17 |
| 5.3.3 | Circular saw blade fixing device | 17 |
| 5.3.4 | Flange dimension for circular saw blades | 17 |
| 5.3.5 | Arbor rings | 17 |
| 5.3.6 | Quick tool/arbor change system | 17 |
| 5.3.7 | Manual adjustment of arbor height | 18 |
| 5.3.8 | Manual adjustment of arbor inclination | 18 |
| 5.4 | Braking | 19 |
| 5.4.1 | Braking of tools | 19 |
| 5.4.2 | Maximum run-down time | 19 |
| 5.4.3 | Brake release | 19 |
| 5.5 | Safeguards | 19 |

| | | |
|----------|---|-----------|
| 5.5.1 | Fixed guards..... | 19 |
| 5.5.2 | Interlocking movable guards | 19 |
| 5.5.3 | Hold-to-run control..... | 19 |
| 5.5.4 | Two-hand control..... | 19 |
| 5.5.5 | Electro-sensitive protective equipment (ESPE) | 19 |
| 5.5.6 | Pressure-sensitive protective equipment (PSPE)..... | 19 |
| 5.5.7 | Enabling control..... | 20 |
| 5.6 | Prevention of access to hazardous moving parts..... | 20 |
| 5.6.1 | Access to the tool below the table..... | 20 |
| 5.6.2 | Safeguarding for straight work..... | 20 |
| 5.6.3 | Safeguarding for curved work..... | 22 |
| 5.6.4 | Safeguarding for tenoning..... | 23 |
| 5.6.5 | Safeguarding the glass bead saw blade..... | 24 |
| 5.6.6 | Guarding of drives..... | 24 |
| 5.7 | Impact hazard..... | 24 |
| 5.8 | Clamping devices..... | 24 |
| 5.9 | Measures against ejection..... | 24 |
| 5.9.1 | General..... | 24 |
| 5.9.2 | Guards materials and characteristics..... | 24 |
| 5.9.3 | Anti-kickback devices..... | 25 |
| 5.10 | Workpiece supports and guides..... | 27 |
| 5.10.1 | Machine table..... | 27 |
| 5.10.2 | Workpiece guiding for straight work..... | 30 |
| 5.10.3 | Workpiece guiding for curved work..... | 31 |
| 5.11 | Safety appliances..... | 32 |
| 6 | Safety requirements and measures for protection against other hazards..... | 32 |
| 6.1 | Fire..... | 32 |
| 6.2 | Noise..... | 32 |
| 6.2.1 | Noise reduction at the design stage..... | 32 |
| 6.2.2 | Noise emission measurement and declaration..... | 33 |
| 6.3 | Emission of chips and dust..... | 33 |
| 6.4 | Electricity..... | 33 |
| 6.5 | Ergonomics and handling..... | 33 |
| 6.6 | Lighting..... | 33 |
| 6.7 | Pneumatics..... | 33 |
| 6.8 | Hydraulics..... | 34 |
| 6.9 | Electromagnetic compatibility..... | 34 |
| 6.10 | Laser..... | 34 |
| 6.11 | Static electricity..... | 34 |
| 6.12 | Errors of fitting..... | 34 |
| 6.13 | Isolation..... | 34 |
| 6.14 | Maintenance..... | 34 |
| 6.15 | Relevant but not significant hazards..... | 34 |
| 7 | Information for use..... | 34 |
| 7.1 | Warning devices..... | 34 |
| 7.2 | Marking..... | 34 |
| 7.2.1 | General..... | 34 |
| 7.2.2 | Additional markings..... | 34 |
| 7.3 | Instruction handbook..... | 35 |
| 7.3.1 | General..... | 35 |
| 7.3.2 | Additional information..... | 35 |
| | Annex A (informative) List of significant hazards..... | 38 |
| | Annex B (informative) Performance level required..... | 40 |
| | Annex C (normative) Stability test..... | 41 |
| | Annex D (normative) Test for braking function..... | 42 |
| | Annex E (normative) Impact test for guards..... | 43 |
| | Annex F (normative) Noise test code..... | 44 |
| | Annex G (informative) Determination of maximum spindle speeds for single piece arbors..... | 47 |
| | Annex H (normative) Rigidity test for pressure pads, hand protectors and guiding steadies..... | 51 |
| | Bibliography..... | 57 |