

ISO 27893:2026-07 (E)

Vacuum technology - Vacuum gauges - Evaluation of the uncertainties of results of calibrations by direct comparison with a reference gauge

Contents	Page
Foreword	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms	3
5 Basic concept and model	3
5.1 General	3
5.2 Sum model	4
5.3 Quotient model	4
5.4 Combination of the two models	5
6 Calculation of uncertainty in the sum model	5
6.1 Total uncertainty -- Sum model	5
6.2 Uncertainty contributions due to reference standard	5
6.3 Uncertainty contributions due to unit under calibration	7
6.4 Uncertainty contributions due to calibration method or calibration conditions	8
6.5 Coverage factor	8
7 Calculation of uncertainty in the quotient model	8
7.1 Total uncertainty -- Quotient model	8
7.2 Uncertainty contributions due to reference standard	9
7.3 Uncertainty contributions due to the unit under calibration	10
7.4 Uncertainty contributions due to calibration method or calibration conditions	11
7.5 Coverage factor	12
8 Combination of the sum and quotient model for error of reading	12
9 Reporting uncertainties	13
9.1 Uncertainty budget	13
9.2 Calibration certificate	14
Annex A (normative) Efficient uncertainty analysis when Type A uncertainties are not negligible ...	15
Bibliography	17