

# ISO 15519-2:2015-06 (E)

## Specifications for diagrams for process industry - Part 2: Measurement and control

---

| <b>Contents</b>    |   | <b>Page</b> |
|--------------------|---|-------------|
| Foreword .....     |   | v           |
| Introduction ..... |   | vi          |
| <b>1</b>           | <b>Scope .....</b>  | <b>1</b>    |
| <b>2</b>           | <b>Normative references .....</b>                                     | <b>1</b>    |
| <b>3</b>           | <b>Terms, definitions, and abbreviated terms .....</b>                | <b>1</b>    |
| <b>3.1</b>         | <b>Terms related to control .....</b>                                 | <b>1</b>    |
| <b>3.2</b>         | <b>Document types .....</b>   | <b>3</b>    |
| <b>3.3</b>         | <b>Abbreviated terms .....</b>  | <b>3</b>    |
| <b>4</b>           | <b>Documentation and process control principles .....</b>             | <b>3</b>    |
| <b>4.1</b>         | <b>Introduction .....</b>   | <b>3</b>    |
| <b>4.2</b>         | <b>Diagram types, structures, and life cycle aspects .....</b>        | <b>4</b>    |
| <b>4.3</b>         | <b>Process control interrelations .....</b>                           | <b>5</b>    |
| <b>4.4</b>         | <b>Information exchange between process and control systems .....</b> | <b>6</b>    |
| <b>5</b>           | <b>Exchange of process control information .....</b>                  | <b>7</b>    |
| <b>5.1</b>         | <b>Symbols for information exchange .....</b>                         | <b>7</b>    |
| <b>5.1.1</b>       | <b>General .....</b>  | <b>7</b>    |
| <b>5.1.2</b>       | <b>Placement of information inside the PCI symbol .....</b>           | <b>8</b>    |
| <b>5.1.3</b>       | <b>Placement of information outside the PCI symbol .....</b>          | <b>9</b>    |
| <b>5.2</b>         | <b>Letter codes .....</b>   | <b>9</b>    |
| <b>5.2.1</b>       | <b>General .....</b>  | <b>9</b>    |
| <b>5.2.2</b>       | <b>Representation of letter codes for process variables .....</b>     | <b>9</b>    |
| <b>5.2.3</b>       | <b>Representation of letter codes for control functions .....</b>     | <b>10</b>   |
| <b>5.2.4</b>       | <b>Sequence of letter codes for control functions .....</b>           | <b>11</b>   |
| <b>5.2.5</b>       | <b>Modifying letter codes .....</b>                                   | <b>12</b>   |
| <b>5.3</b>         | <b>Reference designation .....</b>                                    | <b>13</b>   |
| <b>6</b>           | <b>Representation in general .....</b>                                | <b>13</b>   |
| <b>6.1</b>         | <b>General .....</b>  | <b>13</b>   |
| <b>6.2</b>         | <b>Signal lines .....</b>   | <b>13</b>   |
| <b>6.3</b>         | <b>Graphical symbols .....</b>  | <b>14</b>   |
| <b>6.3.1</b>       | <b>General .....</b>  | <b>14</b>   |
| <b>6.3.2</b>       | <b>Instruments with integrated display .....</b>                      | <b>14</b>   |
| <b>6.3.3</b>       | <b>Multifunction instruments .....</b>                                | <b>14</b>   |
| <b>6.3.4</b>       | <b>Instruments forming a group .....</b>                              | <b>15</b>   |
| <b>6.3.5</b>       | <b>Differentiating of representation .....</b>                        | <b>15</b>   |
| <b>6.3.6</b>       | <b>Graphical symbol "groups" in diagrams .....</b>                    | <b>15</b>   |
| <b>7</b>           | <b>Representation in diagrams .....</b>                               | <b>15</b>   |
| <b>7.1</b>         | <b>Introduction .....</b>   | <b>15</b>   |
| <b>7.2</b>         | <b>Process flow diagram, PFD .....</b>                                | <b>16</b>   |
| <b>7.2.1</b>       | <b>Description .....</b>  | <b>16</b>   |
| <b>7.2.2</b>       | <b>Application .....</b>  | <b>16</b>   |
| <b>7.2.3</b>       | <b>.....</b>  | <b>16</b>   |
| <b>7.2.4</b>       | <b>Representation .....</b>   | <b>17</b>   |
| <b>7.3</b>         | <b>Process and instrumentation diagram, PID .....</b>                 | <b>18</b>   |
| <b>7.3.1</b>       | <b>Description .....</b>  | <b>18</b>   |

|   |                                    |    |
|---|------------------------------------|----|
| 7.3.2   | Application .....                  | 18 |
| 7.3.3   | .....                              | 18 |
| 7.3.4   | Representation .....               | 19 |
| 7.4   | Process control diagram, PCD ..... | 20 |
| 7.4.1   | Description .....                  | 20 |
| 7.4.2   | Application .....                  | 21 |
| 7.4.3   | .....                              | 21 |
| 7.4.4   | Representation .....               | 21 |
| 7.5   | Typical diagrams, TYD .....        | 22 |
| 7.5.1   | Description .....                  | 22 |
| 7.5.2   | Application .....                  | 22 |
| 7.5.3   | .....                              | 22 |
| 7.5.4   | Representation .....               | 22 |
| Annex A (informative) Graphical symbols for connections main process equipment, measurement, actuation, and control ..... |                                    | 24 |
| Annex B (informative) Examples of representation of measurement, control, and actuation tasks ...                         |                                    | 34 |
| Annex C (informative) Diagram examples .....  |                                    | 36 |
| Annex D (informative) Information exchange between process and control system .....                                       |                                    | 40 |
| Annex E (informative) Relationship between terms for closed loop control, measurement, actuation, etc .....               |                                    | 42 |
| Bibliography .....  |                                    | 43 |