

ISO 14617-6:2002-09 (E)

Graphical symbols for diagrams - Part 6: Measurement and control functions

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		2
4 Functional links and junctions		3
5 Point of measurement		5
6 Operation of final controlling elements		5
7 Information-processing functions		10
8 Binary logic functions		20
9 Back-up functions		20
10 Examples of use of symbols in control loops		21
Bibliography		23