

ISO 7-2:2000-09 (E)

Pipe threads where pressure-tight joints are made on the threads - Part 2: Verification by means of limit gauges

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative reference	1
3 Terms and definitions	1
4 Symbols	2
5 Design of gauges	3
5.1 General	3
5.2 Taper full form threaded plug gauges (gauges No. 1 and No. 2)	4
5.3 Parallel full form threaded ring gauge (gauge No. 3)	8
5.4 Taper plain ring gauge (gauge No. 4)	10
5.5 Taper modified thread form check plug gauge (gauge No. 5)	11
5.6 Parallel modified thread form check ring gauge (gauge No. 6)	13
6 Use of gauges and checking of pipe threads	14
6.1 General	14
6.2 Checking of internal taper (Rc) and internal parallel (Rp) threads	15
6.3 Checking of external taper (R) threads	16
7 Gauge dimensions and manufacturing tolerances, checking of new gauges and checking gauges for wear	17
7.1 Gauge dimensions and manufacturing tolerances	17
7.2 Checking of new gauges	23
7.3 Checking gauges for wear	26
7.4 Marking of gauges	28
Annex A (normative) Summary of gauges	29