

# ISO 5171:2009-05 (E)

## Gas welding equipment - Pressure gauges used in welding, cutting and allied processes

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Pressure .....</b>	<b>2</b>
4.1	Unit of pressure .....	2
4.2	Maximum scale reading .....	2
4.3	Maximum pressure mark .....	2
<b>5</b>	<b>Manufacturing requirements .....</b>	<b>3</b>
5.1	Materials .....	3
5.2	Design and dimensions .....	3
<b>6</b>	<b>Safety .....</b>	<b>8</b>
<b>7</b>	<b>Marking .....</b>	<b>8</b>
<b>8</b>	<b>Tests .....</b>	<b>8</b>
8.1	General .....	8
8.2	Design and manufacturing standard .....	9
8.3	Accuracy .....	9
8.4	Torsion test .....	10
8.5	Bend test .....	10
8.6	Case vent test .....	11
8.7	Overpressure test .....	12
8.8	Flammability test .....	12
<b>Bibliography .....</b>		<b>13</b>