

ISO 18592:2009-12 (E)

Resistance welding - Destructive testing of welds - Method for the fatigue testing of multi-spot-welded specimens

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	2
3	Terms and definitions	3
4	Symbols and abbreviated terms	5
5	Specimens	7
5.1	General	7
5.2	Selection of suitable specimens	8
5.3	Specimen fabrication	10
5.4	Specimen geometry	11
6	Requirements for testing machine	21
7	Specimen grips and alignment	22
7.1	General	22
7.2	Shear and peel loading	23
8	Test procedure	24
8.1	General	24
8.2	Mounting the H-specimens	24
8.3	Clamping procedure for the H-specimens	24
8.4	Fatigue test	24
8.5	Test termination	25
9	Test report	27
9.1	Basic information	27
9.2	Presentation of fatigue test results	28
Annex A (informative) Calibration specimen for verifying the load distribution in H-specimens		30
Annex B (informative) Hydraulic grips for the fatigue testing of H-specimens		31
Annex C (informative) Grip for the fatigue testing of H-specimens		32
Annex D (informative) Flow chart -- Data acquisition		33
Bibliography		36