

ISO 7289:2010-01 (E)

Gas welding equipment - Quick-action couplings with shut-off valves for welding, cutting and allied processes

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Types of coupling	2
5	Installation	2
6	Design requirement	2
7	Working requirements	4
8	General test conditions	5
9	Test procedure	7
10	Marking	9
11	Instructions for use	9
Bibliography		10