

# ISO 5175-2:2017-09 (E)

## Gas welding equipment - Safety devices - Part 2: Devices not incorporating a flame (flashback) arrester

---

Contents	Page
<b>Foreword .....</b>	<b>iv</b>
<b>1 Scope .....</b>	<b>1</b>
<b>2 Normative references .....</b>	<b>1</b>
<b>3 Terms and definitions .....</b>	<b>1</b>
<b>4 Design and materials .....</b>	<b>3</b>
<b>4.1 Connections .....</b>	<b>3</b>
<b>4.2 Materials .....</b>	<b>3</b>
<b>5 Requirements .....</b>	<b>4</b>
<b>5.1 General .....</b>	<b>4</b>
<b>5.2 Gas tightness .....</b>	<b>4</b>
<b>5.3 Pressure resistance .....</b>	<b>4</b>
<b>5.4 Non-return valve .....</b>	<b>4</b>
<b>5.5 Pressure relief valves .....</b>	<b>5</b>
<b>5.6 Excess flow cut-off valves .....</b>	<b>5</b>
<b>5.7 Flashback resistance .....</b>	<b>5</b>
<b>6 Methods for type testing .....</b>	<b>5</b>
<b>6.1 General .....</b>	<b>5</b>
<b>6.2 Accuracy of pressure and flow measurements .....</b>	<b>5</b>
<b>6.3 Test gases .....</b>	<b>5</b>
<b>6.4 Gas tightness test .....</b>	<b>6</b>
<b>6.5 Pressure resistance test .....</b>	<b>6</b>
<b>6.6 Non-return valve test .....</b>	<b>6</b>
<b>6.7 Pressure relief valves .....</b>	<b>6</b>
<b>6.8 Excess flow cut-off valve .....</b>	<b>6</b>
<b>6.9 Internal leakage test for cut-off valves .....</b>	<b>7</b>
<b>7 Manufacturer's instructions .....</b>	<b>7</b>
<b>8 Marking .....</b>	<b>7</b>
<b>Annex A (informative) Gas flow measurement .....</b>	<b>9</b>
<b>Annex B (informative) Third party testing information .....</b>	<b>11</b>