

ISO 21904-3:2018-02 (E)

Health and safety in welding and allied processes - Requirements, testing and marking of equipment for air filtration - Part 3: Determination of the capture efficiency of on-torch welding fume extraction devices

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	2
5 Test equipment and materials	2
5.1 General requirement	2
5.2 Test equipment	2
6 Test procedure	4
6.1 Preliminary tests	4
6.1.1 Setting the shielding gas flow rate	4
6.1.2 Measuring the flow rates and determination of leakage	4
6.1.3 Establishing the arcing time for total fume emission rate test	5
6.1.4 Setting up the test equipment	5
6.2 Capture efficiency tests	6
6.2.1 General	6
6.2.2 Test procedure	6
6.2.3 Calculation of the results	7
7 Test parameters for generating capture efficiency data	8
8 Test report	9
Annex A (informative) Equipment notes	10
Annex B (normative) Trial tests	12
Annex C (informative) Examples of test chambers	14
Annex D (normative) Test procedures	16
Annex E (informative) Data processing for test method 3	17
Annex F (normative) Test parameters form to be filled	19
Annex G (informative) Information about the necessity to measure leakage	20
Bibliography	21