

# ISO 13919-2:2021 (E)

## Electron and laser-beam welded joints — Requirements and recommendations on quality levels for imperfections — Part 2: Aluminium, magnesium and their alloys and pure copper

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Symbols and abbreviated terms
5	Evaluation of welds
Annex A	(informative) Examples of determination of percentage (%) porosity
Annex B	(informative) Additional information for the use of this document

Page count: 15